


CAR DETAILS			
Car Manufacturer	Maruti Suzuki	Power Steering	Yes
Model	Ciaz	Shape	
Variant	ZXi	Insurance Type	Comprehensive
Registration no	MH03BSXXXX	Insurance Expiry	22-Jul-2023
City	Mumbai	Number of Owners	1
Fuel type	Petrol	Manufacturing Year	2014
Transmission	Manual	Date of Registration	03-Nov-2014
KM Run (as seen)	63,258 Kms	RTO Location	Mumbai
Colour	White	Hypothecation	No

SELLER DETAILS
Demo
Virar West
Mumbai - Tel - 9594876096



ENGINE **4.2/5**

SILENCER PERFECT CONDITION <p>✓ Exhaust is in perfect condition</p>	RADIATOR/ CONDENSOR PERFECT CONDITION <p>✓ Radiator is in perfect condition</p>
ABNORMAL ENGINE NOISE NO ABNORMAL ENGINE NOISE	OIL LEAKAGE NO LEAKAGE <p>✓ No oil leakage</p>
HOSES GOOD <p>✓ No immediate repair / replacement required</p>	BELTS GOOD <p>✓ No immediate repair / replacement required</p>
PLUGS GOOD <p>✓ No immediate repair / replacement required</p>	FILTERS GOOD <p>✓ No immediate repair/ replacement required</p>

LEGEND

Excellent/Working	Good	Average
Not Working/ (Minor) Work Needed	Damaged/ Major Work Needed	Available ✓ Not Available ✗

*Registration Certificate and/or insurance copy not available at the time of inspection (dealer has said this)

DISCLAIMER: This report (report means product or/and services provided to the customer) is based on the condition of the vehicle on the date of inspection and provides an approximate estimate of the condition on that date. CarTrade Tech Limited ("CarTrade Tech") has relied on the odometer reading for KMs driven as seen at the time of inspection and is not responsible for verifying its genuineness. Except where indicated the parts were in working condition - this report does not take into account the condition of the parts which are not visible or not inspected. The report is in no way a commitment to the condition of the vehicle. All reports are subjective and CarTrade Tech and its associates cannot be held liable in any way due to the use of this report in any way. At no time CarTrade Tech and its associates have any obligations or liabilities in respect of transactions originated on the basis of this report. The price and other terms of any sale of the vehicle shall remain subject to direct negotiation between buyer and seller.

SUSPENSION

3.8/5

<p>SUSPENSION NOISE WHILE DRIVING - FRONT WORK NEEDED </p> <p>✗ Shock absorbers needs replacement</p>	<p>SUSPENSION NOISE WHILE DRIVING - REAR NO NOISE </p> <p>✓ No abnormal noise noticed</p>
<p>STEERING OPERATION WORKING </p> <p>✓ Steering working fine</p>	<p>STEERING LOCK WORKING </p>
<p>WHEEL ALIGNMENT/ BALANCING /WOBBLING PERFECT CONDITION </p> <p>✓ Tyres are aligned and balanced</p>	

BRAKES

2.3/5

<p>BRAKE PEDAL OPERATION PERFECT CONDITION </p> <p>✓ Pedal is fine</p>	<p>BRAKE ASSEMBLY WORK NEEDED </p> <p>✗ Brake needs cleaning</p>
---	---

TRANSMISSION

5/5

<p>GEAR BOX PROPER </p> <p>✓ Gears assembly working fine</p>	<p>AXEL AND BOOTS PERFECT CONDITION </p> <p>✓ Axel working fine</p>
<p>DIFFERENTIAL AND CROWN PERFECT CONDITION </p> <p>✓ Working fine</p>	

ELECTRICAL

3.6/5

<p>INSTRUMENT CLUSTER - WARNING LIGHTS / METERS WORKING </p> <p>✓ All warning lights functional ✓ All meters working</p>	<p>BATTERY CONDITION GOOD </p> <p>✓ No immediate repair / replacement required</p>
<p>ALTERNATOR AND STARTER MOTOR GOOD </p> <p>✓ No immediate repair / replacement required</p>	<p>FUEL PUMP GOOD </p> <p>✓ No immediate repair / replacement required</p>

AC FUNCTION

4.3/5

<p>COOLING GOOD </p> <p>✓ A/C cooling is Ideal</p>	<p>BLOWER FAN GOOD </p> <p>✓ No noise noticed ✓ Working at all speeds ✓ Consistent air flow</p>
<p>HEATING GOOD </p>	

LEGEND

Excellent/Working	Good	Average
Not Working/ (Minor) Work Needed	Damaged/ Major Work Needed	Available ✓ Not Available ✗

*Registration Certificate and/or insurance copy not available at the time of inspection (dealer has said this)

DISCLAIMER: This report (report means product or/and services provided to the customer) is based on the condition of the vehicle on the date of inspection and provides an approximate estimate of the condition on that date. CarTrade Tech Limited ("CarTrade Tech") has relied on the odometer reading for KMs driven as seen at the time of inspection and is not responsible for verifying its genuineness. Except where indicated the parts were in working condition - this report does not take into account the condition of the parts which are not visible or not inspected. The report is in no way a commitment to the condition of the vehicle. All reports are subjective and CarTrade Tech and its associates cannot be held liable in any way due to the use of this report in any way. At no time CarTrade Tech and its associates have any obligations or liabilities in respect of transactions originated on the basis of this report. The price and other terms of any sale of the vehicle shall remain subject to direct negotiation between buyer and seller.

TYRE LIFE


3.4/5

FRONT RIGHT TYRE	70%		FRONT LEFT TYRE	70%	
REAR RIGHT TYRE	70%		REAR LEFT TYRE	70%	
STEPNEY TYRE	60%				

EXTERIOR

3.2/5

CAR BODY	MINOR WORK NEEDED	HEADLIGHTS	WORKING
✗ Minor dents and scratches		✓ Main bulb working (dipper)	✓ Parking bulb working
WIPERS	WORKING	INSIDE & OUTSIDE REAR VIEW MIRRORS	WORKING
✓ Wiper blades are ok	✓ Wiper motor is working fine	✓ Mirror and casing OK	✓ Electric folding functional
		✓ Adjustment lever functioning ok	
TURN INDICATORS	WORKING	TAIL LIGHTS	WORKING
✓ Side indicator light working		✓ Main bulb working	✓ Parking bulb working
		✓ Reverse indicator bulb working	



- DE - Dent
- CR - Crack
- SC - Scratch
- CD - Cold Dent
- CS - Corrosion
- RE - Repainted
- PD - Paint Defects
- RP - Replaced
- RD - Repaired
- SO - Seal Open

LEGEND










Excellent/Working	Good	Average
Not Working/ (Minor) Work Needed	Damaged/ Major Work Needed	Available ✓ Not Available ✗

*Registration Certificate and/or insurance copy not available at the time of inspection (dealer has said this)

DISCLAIMER: This report (report means product or/and services provided to the customer) is based on the condition of the vehicle on the date of inspection and provides an approximate estimate of the condition on that date. CarTrade Tech Limited ("CarTrade Tech") has relied on the odometer reading for KMs driven as seen at the time of inspection and is not responsible for verifying its genuineness. Except where indicated the parts were in working condition - this report does not take into account the condition of the parts which are not visible or not inspected. The report is in no way a commitment to the condition of the vehicle. All reports are subjective and CarTrade Tech and its associates cannot be held liable in any way due to the use of this report in any way. At no time CarTrade Tech and its associates have any obligations or liabilities in respect of transactions originated on the basis of this report. The price and other terms of any sale of the vehicle shall remain subject to direct negotiation between buyer and seller.

INTERIOR






4.7/5

<p>POWER WINDOWS - FRONT WORKING </p> <ul style="list-style-type: none"> ✓ Window operating smooth ✓ Power window switch working ✓ Power window motor working 	<p>POWER WINDOWS - BACK WORKING </p> <ul style="list-style-type: none"> ✓ Window operating smooth ✓ Power window switch working ✓ Power window motor working
<p>CENTRAL LOCKING WORKING </p> <ul style="list-style-type: none"> ✓ Central locking working ✓ Remote working ✓ Motors functioning of all doors 	<p>HEADLAMP/INDICATOR SWITCHES WORKING </p> <ul style="list-style-type: none"> ✓ Headlight switch working ✓ Wiper switch working ✓ Side indicator switch working
<p>HORN WORKING </p> <ul style="list-style-type: none"> ✓ Horn working 	<p>TOOL KIT AVAILABLE ✓</p> <ul style="list-style-type: none"> ✓ Wheel spanner available ✓ Warning Triangle available ✓ Jack with handle available
<p>CONDITION OF SEATS GOOD </p> <ul style="list-style-type: none"> ✓ Seats in good condition 	<p>ROOF WEAR & TEAR GOOD </p> <ul style="list-style-type: none"> ✓ Roof lining in good condition
<p>SEAT RECLINERS WORKING </p> <ul style="list-style-type: none"> ✓ Seat recliner working ✓ Seat recliner lever functional 	<p>SEAT BELTS WORKING </p> <ul style="list-style-type: none"> ✓ Seat belt operating smoothly ✓ Seat belt lock working

ACCESSORIES

<p>ALLOY WHEELS AVAILABLE ✓</p>	<p>SEAT COVERS AVAILABLE ✓</p>
<p>FLOOR MATS AVAILABLE ✓</p>	<p>FOG LAMPS AVAILABLE ✓</p>
<p>MUD FLAPS AVAILABLE ✓</p>	<p>REVERSE CAMERA AVAILABLE ✓</p>
<p>SOUND SPEAKERS AVAILABLE ✓</p>	<p>MUSIC SYSTEM AVAILABLE ✓</p>

LEGEND

Excellent/Working 	Good 	Average 
Not Working/ (Minor) Work Needed 	Damaged/ Major Work Needed 	Available ✓ Not Available ✗

*Registration Certificate and/or insurance copy not available at the time of inspection (dealer has said this)

DISCLAIMER: This report (report means product or/and services provided to the customer) is based on the condition of the vehicle on the date of inspection and provides an approximate estimate of the condition on that date. CarTrade Tech Limited ("CarTrade Tech") has relied on the odometer reading for KMs driven as seen at the time of inspection and is not responsible for verifying its genuineness. Except where indicated the parts were in working condition - this report does not take into account the condition of the parts which are not visible or not inspected. The report is in no way a commitment to the condition of the vehicle. All reports are subjective and CarTrade Tech and its associates cannot be held liable in any way due to the use of this report in any way. At no time CarTrade Tech and its associates have any obligations or liabilities in respect of transactions originated on the basis of this report. The price and other terms of any sale of the vehicle shall remain subject to direct negotiation between buyer and seller.



REFURB DETAILS

Refurb Name	Estimated Cost	Remarks
Suspension Noise While Driving - Front	7000	Both shock absorber need to replace
N/A	5000	Service Required
Oil	2000	Engine oil need to replace
Car Body	10000	4 panels painting required
Brake Assembly	1500	Breke need to cleaning
Total	25500/-	

DISCLAIMER: This report (report means product or/and services provided to the customer) is based on the condition of the vehicle on the date of inspection and provides an approximate estimate of the condition on that date. CarTrade Tech Limited ("CarTrade Tech") has relied on the odometer reading for KMs driven as seen at the time of inspection and is not responsible for verifying its genuineness. Except where indicated the parts were in working condition - this report does not take into account the condition of the parts which are not visible or not inspected. This report is in no way a commitment to the condition of the vehicle. All reports are subjective and CarTrade Tech and its associates cannot be held liable in any way due to the use of this report in any way. At no time CarTrade Tech and its associates have any obligations or liabilities in respect of transactions originated on the basis of this report. The price and other terms of any sale of the vehicle shall remain subject to direct negotiation between buyer and seller.



BUYING ESTIMATION

Minimum Buying Price	Maximum Buying Price
420000	440000



IMAGES

https://www.cartradeexchange.com/mob/sellleads_images/yXNpJlze- ACq1e7bnAQ



TERMS & CONDITIONS

CTE/EVALUATION ID/1984199, EVALUATION DATE:07/06/2023

DISCLAIMER:

This report (report means product or/and services provided to the customer) is based on the condition of the vehicle on the date of inspection and provides an approximate estimate of the condition on that date. CarTrade Tech Limited ("CarTrade Tech") has relied on the odometer reading for KMs driven as seen at the time of inspection and is not responsible for verifying its genuineness. Except where indicated the parts were in working condition - this report does not take into account the condition of the parts which are not visible or not inspected. The report is in no way a commitment to the condition of the vehicle. All reports are subjective and CarTrade Tech and its associates cannot be held liable in any way due to the use of this report in any way. At no time CarTrade Tech and its associates have any obligations or liabilities in respect of transactions originated on the basis of this report. The price and other terms of any sale of the vehicle shall remain subject to direct negotiation between buyer and seller.

DISCLAIMER: This report (report means product or/and services provided to the customer) is based on the condition of the vehicle on the date of inspection and provides an approximate estimate of the condition on that date. CarTrade Tech Limited ("CarTrade Tech") has relied on the odometer reading for KMs driven as seen at the time of inspection and is not responsible for verifying its genuineness. Except where indicated the parts were in working condition - this report does not take into account the condition of the parts which are not visible or not inspected. The report is in no way a commitment to the condition of the vehicle. All reports are subjective and CarTrade Tech and its associates cannot be held liable in any way due to the use of this report in any way. At no time CarTrade Tech and its associates have any obligations or liabilities in respect of transactions originated on the basis of this report. The price and other terms of any sale of the vehicle shall remain subject to direct negotiation between buyer and seller.